

SSO Maintenance Report

Date of Occurance	Address	Blockage Reason 1	Blockage Reason 2	Volume/Gallons	Responsibility	Removal Method	Receiving Waters	Mitigation Used on Untreated Waters	Actions to mitigate future SSO
05/10/15	19012 Jodi	Rain		200	Village	Sewer Jet			Line maintenance
06/17/15	17930 Homewood	Rain	Tree roots	10	Village	Sewer Jet			Line maintenance
06/17/15	1246 Thomas	Rain		10	Village	Sewer Jet			Line maintenance